







1 JAMB DETAILS @ STAIR #1




2 HEAD DETAIL @ DOORS #201 & #202




3 HEAD DETAIL @ DOOR #203




4 HEAD DETAIL @ DOOR #204





5 JAMB DETAILS @ DOOR #204





6 PANEL TOP DETAIL





7 PANEL BOTTOM DETAIL





8 SILL SECTION @ DOOR #203



10 JAMB DETAILS @ STAIR #2



11 SILL SECTION



12 SILL SECTION

